

## **7.2 - Best Practices**

7.2.1 - Describe two best practices successfully implemented by the Institution as per NAAC format provided in the Manual.

Response:

Best Practice : No. 1

01. Title of the Practice:

Weir construction on Kathani River

02. Objectives of the practice:

01. To raise underground water level near the construction area.

02. To hold water in river for some more time.

03. To know the importance of the labour work to the NSS students.

03.. The Context:

The volunteers of NSS under the guidance and supervision of NSS Program officers constructed the weir on the river Kathani on 16/04/2022 at Japra Rajghata village. This village is adopted village by NSS and special NSS camp was organized in the village by the college administration for seven days.

04. The Practice:

Under the guidance of NSS program officers Dr. J. G. Weekey and Shri. S. P. Dhamane, the NSS volunteers made survey about underground water level in the village Japra Rajghata. They noticed about the water


problem in summer season and some responsible villagers suggested the NSS program officer to construct the weir on the river in which is flowing beside the village. All water was continuously flowing in the river and in the mid of summer it got dry. They decided to hold water in the river for some more time and to raise underground water level by constructing weir on it. Near about 35 NSS volunteers constructed weir on the river Kathani. The size of weir was 4 feet wide, 5 feet in height, and 45 feet long in length. They constructed weir with the help of river sand and empty cement bags. NSS volunteers filled sand into the empty cement bags and after sealing it made the wall like weir on river Kathani. After construction of weir water of the river hold more time and excess water overflowed from the weir wasteware.

05. Evidence of Success:

This practice is accomplished during the academic year 2021-2022. The report and documentary proofs are kept ready by NSS Department. And the report of the event is submitted to Gondwana University.

06. Problem Encountered:

The NSS volunteers who were engaged in construction of weir faced few minor problems during work. The tools such as spades, plastic tubs were not sufficient for the work. And financial problem is also one problem during the practice.



## 7.2. Best Practice : No. 1

### Weir construction on Kathani River –

